## SOW CHANGE PROPOSAL

SOW-02-833-1-8B477B-2/1 SOW-03-833-1-8B477B-2/1 SOW-04-CBG-8B477B-2/1 Change 1 Change 1 Change 1 6 Sep 2002

STATEMENT OF WORK (SOW)

for the

Inspection and Repair Only As Necessary (IROAN)

of the

NORTH FINDING MODULE WHEEL AND SERVO MOTOR SUPPLY ASSEMBLY A2 CARD NSN 5999-01-212-1612

SOW-02-833-1-8B477B-2/1 SOW-03-833-1-8B477B-2/1 SOW-04-CBG-1-8B477B-2/1

## Change Paragraph 1.0 from:

NSN 5999-01-212-1612

## To read:

NSN 5998-01-212-1612 to reflect the new federal supply class of 5998.

If approved, does this proposed change have the potential to have an impact on the cost or schedule? \* Yes /\_/ or No /X\_/ (Place and X in the appropriate block)

\*Changes that have the potential to impact cost or schedule will be reviewed by Maintenance Directorate (MD) and an impact statement provided to SCMC. Changes that do not have the potential to impact cost or schedule may not be reviewed by MD.

Change Submitted by:

Darrell Taylor

Equipment Specialist

AFSS-FSS

MARCORSYSCOM, Albany GA

Change Approved by

Fred Reynolds

Logistics Management Specialist

**AFSS-FSS** 

MARCORSYSCOM, Albany, GA

6 September 2002

6 September 2002